

EPS SSR-5b
POWER BUS LOSS: RPCM Z13B B

ACTION	EQUIP/FUNCTION LOST	CREW INDICATION	NOTES
	RPCM Z13B B (Type V)		
Power On PCU PCS Z1: EPS RPCM Z14B B sel RPC 15 cmd Close ✓Position - CI	SPDA Z13B Htr SPDA Z14B Htr CMG 1 Ext Htr CMG 4 Ext Htr PCU 2 Htr DDCU Z13B Htr DDCU Z14B Htr EEATCS Non-op Htr A-1	<u>Caution Messages:</u> <u>Advisory Messages:</u> RPCM Z13B_B Loss of Comm - Z1	① EEATCS, CMG, and PCU heaters are not redundant; possible loss of equipment. PCU is powered to provide some heat.
On MCC Go Perform RPCM REMOVE AND REPLACE, all (SODF: OSO).	CMG 2 CMG 3	<u>Telemetry:</u> PCS Z1: EPS Z1:EPS RPCM Z13B B - not Active	
	PCU 1		
	S-Band SASA S-Band XPDR S-Band BSP KU-Band SGTRC KU-Band SGANT		